




KDL-DC/AC SERIES INSTALLING AND USING ILLUMINATION

1. THE PICTURE OF STRUCTURE




B. Put two ⑧ insert ④ one by one




D. According to ⑬ above of ⑪, adjust the both balance height of ⑪. Then locked ⑫

E. Enclose printing fabric (KDL-DC)





F. Readjust ⑭ make ② drive while ① hanging up and locked ⑫



Special Note:
don't pull out the connecting line of bottom(KDL-DC).


② Drive pipe must be hang up while driving ① in the mainframe crust.

Drive pipe ② can take out



2. INSTALL PROCESS

A. Separate ④ to make both of left and right horse level



Illuminate:

The picture adopt white printing with coat
The width of picture are total machine wide minus 65-
The max of picture height are 1900mm.